

RECEIVED

JAN 30 2001

DIVISION OF
OIL, GAS AND MINING

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
1594 West North Temple - Suite 1210
Box 145801
Salt Lake City, Utah 84114-5801
Telephone: (801) 538-5291
Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) 1/2000 To (mo./yr.) 1/2001
 2. DOGM File Number (Mine No): 5 10361017
 3. Mine Name: GREEN BEETLE
 4. Mineral(s) Mined (or permitted to mine): MICACEOUS QUARTZ SCHIST
 5. Type of mine ☒ Surface Mine or ☐ Underground Mine
 6. Legal Description (Location of Lands Affected):
1/4, 1/4, SE 1/4, Section 36, Township 11N, Range 16W
1/4, SW 1/4, NW 1/4, Section 31, Township 11N, Range 15W
1/4, 1/4, 1/4, Section, Township, Range
 7. Name of Operator or Company: UTAH BUILDING STONE SUPPLY
 8. Permanent Street Address: 842 WEST 400 NORTH
City, State, Zip: WEST BOUNTIFUL, UTAH 84087
Phone: 801-295-0601 Fax: 801-295-0601
 9. Company Representative (or designated operator):
Name: WILLIAM L BOWN
Title: OWNER
Business Address: SAME AS #8
City, State, Zip: _____
Phone: _____ Fax: _____
- ☐ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was there any mine related activity during the past year? Yes ☒ No ☐
2. If no - what was the last year of activity? _____
3. If yes - how much ore or mineral was mined? 301.736 TONS ✓

4. Briefly describe the type of work performed, volume of material moved, and any new or additional surface disturbances that occurred during the past year.

STONE REMOVED WITH EXCAVATOR TO PROCESS AREA. ALL
REMOVAL TOOK PLACE WITHIN EXISTING DISTURBANCE PERIMETER.
NO NEW DISTURBANCE.

5. How much **additional acreage** was disturbed during the past year? NONE

6. How much acreage was **reclaimed** during the past year? 3.2 ACRES

7. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.

UPPER QUARRY AREA WAS FILLED, GRADED, AND RE SEEDDED,
ACCESS RD WAS PULLED BACK AND RIPPED.

8. What is the **total** disturbed acreage of entire project at years end? 1.5

9. Briefly summarize any mining and/or reclamation plans for the upcoming year.

INCIDENT TO OUR LOSS OF ALL SITLA LEASES IN THE AREA WE
WILL NOT BE EXTRACTING STONE FROM SEC. 36. WE WILL WORK EX-
CLUSIVELY IN SEC. 31. WE WILL COMPLETE RECLAMATION OF PIT #1 &
#2.

NOTE: Section III., "Additional Information" applies only to **large mining operations**.

III. Additional Information

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print):

WILLIAM L BOWN

Title of Operator:

OWNER

Signature of Operator:

William L Bown

Date:

1-29-01